Turner

Turner Construction Company 2001 N. Lamar, Suite 100 Dallas, TX 75202 Phone: (214) 721-8400 Fax: (214) 721-8493

4/6/11

Mr. Bill Burke Collin County 4600 Community Ave. McKinney, TX 75071

RE:

Collin County Courthouse Addition

Owner Project #R0508003.00 Turner Project #1692600

SUBJ: PCO #007 R4 - Owner Directive #03 Replace Conduits & RFI #128.

Dear Mr. Burke:

We have finalized the required quotations for PC-007 R4 - Owner Directive #03 Replace Conduits & RFI #128.

We have reviewed the scope of work and have verified that all extra work items are in compliance with our contract agreement. Attached is a detailed itemization of the extra costs. Total amount of this request is **Seven Thousand Five Hundred Sixteen dollars** (\$7,516.00).

If you have any questions regarding this Change Order Request, please call me at your earliest convenience.

Please review and acknowledge your approval in the space below. Once approval is achieved, we will expect this PCO to be included in a forthcoming Change Order.

Best Regards,

J. Leas

John A. Leos

Approved by:

Collin County

Date

49.11

Date

cc: Brad Harris & Sara Hoglund- Collin County
Brian Nicodemus- PGAL
Matt Nail, Suhel Rahman, & Ronnie Holcomb- TCCo

Turner

PCO No.: 007 R4

PCO Title: Owner Directive #03 & RFI #128.

Project: Collin County Courthouse Addition

Project No.: R0508003.00

Туре	Company	Description	Subcontractor Base Price	Subcontractor W/C & GL	Subcontractor Total Price
			A	В	C = A+B
Subcontractor	SecureNet	500 LF of 18/6 & 18/4 Cable & Connections. Scope reflects cost difference between requested scope and original contract scope in regard to security conduits to gates. This revision of this cost		98	2,967
Subcontractor		proposal provides an agreement to the noted deduct for this scope of additional work as a trade for use of existing conduits and a reduction of			
Subcontractor	KL Enterprises	conduit quantities. Re-pull, re-terminate, & re-test cable for CCTV Camera, Intercom, Vehicle	(1,100)	(38)	(1,138)
Subcontractor	ISI	Loop, and Card Reader.	4,738	162	4,900
			-	-	-
				-	

-			-	-	
-			-	-	
-			-	-	-
				-	
					-
-			-	-	-
		Subtota	6,507	222	6,729

10% OH&P 787 Total Cost \$ 7,516

Notes: